

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No 128073

RECEIVED FROM Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080188-6

DATE REC'D 1-15-57
P. O. NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	VENDOR PACKING SLIP NO.
322	000000	20010	0	0	00	00	00	
CHARGE TO	DRAWING NO. AND DESCRIPTION						QUANTITY	REMARKS
QUANTITY RECEIVED							ACCEPTED	REJECTED
4	738266 BEARING BEARING ASS'T						4	
INTER FILE 2757								
RECEIVED BY	INSPECTED BY	DATE	REJECTS RETURNED ON SHIP. MEMO NO.					
W. H. H.	QUA	1-15-57						

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA 3, CALIF.

No 128075

RECEIVED FROM

DATE REC'D 1-16-57
P. O. NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	VENDOR PACKING SLIP NO.
322	000000	20013	0	0	00	00	00	
CHARGE TO	DRAWING NO. AND DESCRIPTION						QUANTITY	REMARKS
QUANTITY RECEIVED							ACCEPTED	REJECTED
4	738265 WIRE ASS'TY TENSION SENSOR						3	
SO SUPPLEMENT 100 / 128075								
RECEIVED BY	INSPECTED BY	DATE	REJECTS RETURNED ON SHIP. MEMO NO.					
W. H. H.	QUA	1-16-57						

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080188-6